NCDOT TEAAS Ordinance Report

Municipal Speed Zones

The Board of Transportation has delegated to the Secretary of Transportation the authority to adopt and promulgate all rules and regulations and ordinances regulating traffic on the highways pursuant to authority of N.C.G.S 143B-350 (g) (see 19ANCAC 4A.0004).

The State Traffic Engineer is subdelegated the authority by the Secretary of Transportation to adopt and promulgate all necessary rules, regulations and ordinances for the use of and to police traffic on state highways, and to set, change, or extend route numbers on the Primary Highway System of North Carolina pursuant to authority of N.C.G.S 143B-350(g) (see 19ANCAC 4A.0004).

Pursuant to that delegation, the State Traffic Engineer hereby adopts and promulgates the following ordinances based on traffic and engineering studies performed by the Traffic Engineering Branch, Department of Transportation, and in accordance with General Statute 20-141.

COUNTY CALDWELL

DIVISION 11

DECLARE THE FOLLOWING

County / Municipality	Ordinance Number	Effective Date		Route	Car Spd Lmt	Trk Spd Lmt	Description
CALDWELL	1005898	10/23/1971	SR	1146	35	35	Miller Hill Road (SR 1146) from the southern corporate limitapproximately 0.80 mile north of SR 1149, to South Bypass (NC 18 Bypass).
CALDWELL	1005899	10/23/1971	SR	1531	35	35	Powell Road (SR 1531) from Glenview Street to the northern corporate limit, approximately 0.05 mile south of Shelby Lane (SR 1575).
CALDWELL	1005902	10/23/1971	NC	18	45	45	East Harper Avenue (NC 18-NC 90) from North Boulevard (US 321) to East Boulevard (NC 18-NC 90).
CALDWELL	1005903	10/23/1971	SR	1180	45	45	McLean Drive (SR 1180) from Norwood Street (US 321-A) to South Boulevard (US 321).
CALDWELL	1005904	10/23/1971	US	321ALT	45	45	Norwood Street (US 321-A) from the corporate limit (approximately 50 feet southof Kincaid Road (SR 1170), northto a point 0.05 mile north of Waycross Drive (SR 1173).



BEVERLY EAVES PERDUE
GOVERNOR

EUGENE A. CONTI, JR. SECRETARY

October 27, 2011

To whom it may concern:

Original package cannot be found. Folder contains TEAAS generated report.

Lisa N. Avery

Traffic Safety Project Engineer

WEBSITE: WWW.NCDOT.ORG